FORM NO. 4



SOMERVILLE FIRE DEPARTMENT FIRE REPORT

	LNC.
	7
ļ	•
١	C
I	C
ı	ŧ

DATE: 6/27/16	SOM / BOLLICE:
DATE: 4/27/10	SOM/FIRE INVESTIGATION UNIT:
DATE:	STATE FIRE MARSHALL:
	INVESTIGATED BY:
	NOTIFIED:
REASON - AND WHO WAS	IF SUSPICIOUS, VIOLATION OF LAW, OR UNABLE TO DETERMINE:
	PROBABLE CAUSE: CARCKESI d'Apral ot cigarette
has.	ALL OUT: 2306 has. TIME OF DISMISSAL OF DETAIL:
3RD: 1905 hrs. OTHER:	
time: 1827 hrs.	TYPE OF ALARM: STILL ALARM () TIME: hus. 80x ALARM (W 80x # 3 76 TIME:
0. ()	INSURANCE CO.: TEL/NO.
0. ()	INSURANCE AGENT: TEL/NO. (
(BUSINESS) ()	TELEPHONE NO.: [HOME] (617) 501 9678 [BUST
STATE: MA ZIP CODE: 02/45	CITY/TOWN: NewTon STATE
Rd	TREET & NO.) 11 ELLISON
	OWNER: Jing PAN
	LOCATION OF INCIDENT: /// 6/exwood Rd
INC. CODE: ///	FIRE

FIRE BUILDING

676 698 (17	
617 301 0485	MATThew CHANG
617 839 2172	31d ELizabetH BAINES
617 680 9486	and ETHAN Gifford
978 766 9611	Andrew Low
413 687 7561	Andrew GNATEK
4814 486 619	151 Michael BARNES
TEL/NO.	FLOOR: NAME:
	OCCUPANT INFORMATION
ot operate, None Present)	SUPPRESSION SYSTEM PERFORMANCE: None Present but did not operate, None Present)
ot operate, None Present)	DETECTOR PERFORMANCE: D, of NoT operate - No batteries (Operated Properly, Present but did not operate,
Floor, Structure, Etc.)	EXTENT OF DAMAGE: FLAME: STRUCTURE to Area, Room, F.
CONTENTS / DR, DAG	ESTIMATE OF DAMAGE: BUILDING \$300,000 CO
	TYPE OF OCCUPANCY: BOAR I. WS Hows C. (General Type)
PARTITIONS: TAM &	WALLS: FRAME, Etc.) FLOORS: Wood Joist, Etc.)
Wood FRAM & (General - Type)	HEIGHT: CONSTRUCTION:

STORY OF THE FIRE

or floor openings it extended; how pumpers,ladder trucks and other equipment were placed and how fire was finally controlled where fire apparently started and what material it burned; progress of fire on arrival of Department; through what door, window lf loss was large, give reasons. Mention any injuries or loss of life as a result of the fire. On all fires in buildings, and where appropriate on other alarms, write following a story of the fire in narrative form. Describe

ex1 : rquishmen? 6 3pd Adupaced Bul PORc/+ 5/8 8 150 4-3. WUMB-Floor building 12/0 Paul , NA 1000 1000 cps calion 5000 Ant 6 00/10 0 1 window KEAR the Their COMPANIES 6 0 SIRVELL Both たっと ACCIUA And 2118 SIRUCK building 40 window 5,0% Knock 120 300 70 3/2 Taken mouth CAS 0// OVERHAUL 742 persons And Lines HEALY pble arrival メズ Floor. Floor 2000 And There メイト 50,00 12/2 20000 Cy cours 2) 1905 Hes. 1270 And 2 2 20050 calle Removed 7 1-3 0 That rescue 7% 0 } 5000 1 * 1002 WAS building SIRVE COMP ANIES 6.6 1/2c 7-100x 6-3 other CARAJA ノんへ There 41105 47710 BOAV \. } X build ing 3 more Rescued Brd 1018 16 Repositione /www/ RIPA were Spo Me. 226 Alman women 644512 lange ! ex// 155157 Smoke 907 *}*) OCCUTEd Additiona mester 7,23 STRUCTURE. porches asuished 50 Pakerex CON WAS secont 2/0024 Rox ShowING 1800 047 The people Alliva 70-7 16/EK 4

(MARRATIVE CONTINUED)

Siding.	Glexwood Rd	CARRIA TO 10.	was also Re	ore was nele	The Hospital	sky off th	To work A	The STREET	Ladden 2.	The house	operations	The STAVETU	put thee	On All 7h
Siding.	· From The	CHARLE TO 107 Glenwood Rd And more severe damage To 113	WAS Also Released LAST NIGHT. There was also some minor	One was neleased. The woman prescued From The Thind Floor	The Hospital For Taratment. One was Kept overlight and	shit oft the power. We had Two Finetighters Taken To	To work Around it For 30-40 minutes until Edison	The Street And was A major problem As the Co's had	LAdder 2. IT was snapping And bouncing All over	The house And was hanging over The cab of	operations was A Live wine that broke off From	The Staucture. An odd. Trough Horard Hundering	gut there there in the Root To help vert. In The	on All Three Floor And The ATTIC. LAdder Co's
	end pled heat	And more Se	Night. There	Ar Dascued	T. One was k	had Two Fir	~ 30 - 4c m , m	major paobl	NAPPING AN	NO ENTER	wire that	1. Trough HAZ	The Root To	I The ATTIC
10/4	That solted	evere damage	uns also some	From The The	cpt oversigHI	petighters To,	Jes until E	lear As the c	& bouncing A	The cab of	broke off F	aid Huder	help vest.	c. Lodden
	The lings	76 113	minox	Ad Floor	T And	Ken To	d,500	o's had	11 over		ROM	1,20	672	5,0

RESPONSE TO FIRE

C-5 ()	C-3 [K	C-2A ()	c-2 (K	<u></u>	ENG. 6 (1)	ENG. 4 (W	ENG. 3 1 W	ENG. 2 1 W	ENG. 1 (W	SOMERVILLE COMPANIES
					M-1 ()	LAD. 3 (W	LAD. 2 1 W	TOW. 1 (V)	ENG. 7 (V)	PANTES
THE COMPLETE	Ole Limber			OTHER:	EVELOTENG. # 1 BOTH-LAD. # L-18	BOST ENG. # 32 BUSTOWLAD. # LA	CAMB ENG. # 4 CholsentAD. # J-1	ARI ENG. # 2 CAMB LAD. # 1	Modfan teng. # 5 ENG. #	MUTUAL AID COMPANIES





Massachusetts Fire Incident Reporting System - Basic

Y_MILY	I-Z 61t	7 *	JEKLA OZE	юяч 📙					anoinamiona and effect. Any a Tine Marshal's	io" cause ai	ıst brobabl	չա,, թաթ "	entacy of repe nt "most likely	рекеји керкеге	obam snoit It of sa noit	ucbiescupu and evalua
		эректу	ED OSE BRO	I WIXE		150,000	sjuəjuo						- 4 3 - 1			
• • • • • • • • • • • • • • • • • • • •		SE	AVL BECE	ZVH		000,008	 Торену \$	d		anosot li xo osot bovioos				الـATE إدى رغ	VENT FAction Ta	12 IgnoitibbA
	Пкпомп	nn 🗖				anday 1	E-INCIDEN	Яd		income ji w	E 344 420	Other SX Ch		— ·	_,,_,,	
Scoupants Occupants	nooO bomob MotA 1'nbiO	a 7 ⊠ 5 D	ECTOR:	บาลด		000,001	 Ф «изии»	13							rT noiteA l	
			Civilian	1.1.10		000,001	<u> </u>		 		Z 	- EW3		IGUISH	AITX3	11
<u> </u>		0	Pire Service			300,000	roperty \$	d .	LS		<i>L</i> 1	noisson	ldn _S	_% (]) t	сцои Дакс	A yusmird
7		0	colume 2 said		SuoN				Personnel	şnjı	sieddA			∃∩	RESC	55
səiminl	stpt	ro(]	* SHLTVI	nsvə H		SECTION SE	EL \$ LOSSE	ES			* SECES	вего	9	*	S LVKEN	VC.LION
Special Study Value	#OL #	ybut& lei	oods	2306		01/72/8	Cleared	ijinU Jas.	T 🔲	лодширсі.	ir Incident	ગ્યા ગ	mShioring C	IIO3 ciodT - *	/Received	VIO CUAGO
				2200		01/72/9	polloun	юЭ				1.1.	AM	9/1/1 \$60/1	<u>ι</u>	,5,1;, v
pinisiO	surintA	oon wo		1828		01.72/8	*lsv í ri/	Į.	. 🗆 '			ľ	1	25057 6+071		[
ı	3	t		1827		01/72/8	* arsel A		se annes spiritule		รออนยุเร	umoura	bəxilidə	\$6082 N 01041]	и Туре	IODIOM
,		1	1 1	əmiT	'	Date	ı		Check b				mobion	Chical I		
						(0000 si nlginbiN	& LIMES (N	Satad	3	ı			I	l CBILICVT		l
				ildeoildgs as ,enoil	roonib ro	Cross street	ade Plus 4	oD qiZ	State					Çity	шооу/а	otin8/JqA
							- S	120	AM				רר⊑	SOMERVI		
Census Tract	xijjng	əd	Street Ty	\$		<u>'</u>	•		' '		vrlgiH 10 1	oons s	dlerq 180d	Number/Mile	1	1
3602			ВD							OD	OOMNE	าอ		111		
mao3 banlbfiW r	no bəbivərq	l si ssərbi	ar Juoddont ac	Check this box			Directions] 9 o) ju	ээвірА 🔲 टे То т	.4 🗌 Bosi	lo mori ni	□ € noi	2 🔲 Intersect	sserbbA teen8	⊠ ! ∗ NC	LOCATIC
							* ə.msodx	<u> </u>	nt Number *	obionl	nottet2	* 1	bicd inobiont	* olai?		DIG#
 γήνί.	ibA oM □		Change	อาอุเอ	o 🔲		000		9809	,	НФ		01/12/9	AM	t/	.771






Massachusetts Fire Incident Reporting System – Fire

							Some	- Equipment Power So	
	.Hatani of a	se moved by one person, locations, and requires no tool	Portable equipment morreally earr b is designed to be used in multiple l	ortable 🔲 2 Stationary	a i 🗀 :Aunte	INTAO9	,		
Year	Scrial Mumber		[əpo]	N		bner8	មហ្សាយគឺ) យ	Equipment Involved	
					C	ON 🛭 Mone > Skip to 6			ы 📘
	imated Age of Person Involved	cutally disabled	3 Unattendec m 4 Possibly m 5 Physically 7 Physically		ງ ດາ ສີຍາກຖະການດ ົ	Source Pactor (กงรับรูปเรองก	Intentional	
	มขอย น เมตเอะ	bərinqıni gurb\lodoə	onoM ⊠ qsolaA 1 ☐; de ydisso9 2 ☐	ARDED (1)			Skib to section	Exposure report	
	IGNILLION	LORS CONTRIBUTING TO	Mone HUMAN FACT	SUTING TO IGNITION	ORS CONTRIB	EVC.I.C	Y.	VICE OF ICULTION	ं 🖪
	payual is	Type of Material Fir							
	FABRIC	14							
	mon term or mail brouge	* botingl lerid moll	aged Goods for Sale hir or Service	สอยส ธ 🔲 3 มีขอห	E fairsteM	ətis-nO		Veres Burned	
	AFOR	121	Storage or Warchousing essing or Manufacturing	l Baik			а рио инр	anol/ 🖾	
		Heat Source *	aged Goods for Sale iir or Service	T 3 Buck	Material 2	olis-nO		bovlovni sgaiblia8 #	
	CIGARETTE	19	Storage or Warchousing essing or Minuthering	2 Proc		bov	doval 108 sgait	atiu81 🗔 📗 🖹	
		* nigirO to senA	aged Goods for Sale iir or Service	□ 4 Repa	Material 1	otiz-nO	stinU ;	gnivid To # bolsmitsE	
	РОРСН	7.2	Storage or Warchousing Storage or Marchousing	oo.a z 🔲			Residential	Z 🗆 🗆 Not 1	
		ICHILION	1	RODUCTS 🖂 None	ATERIALS/PI	C ON-SILE W		OPERTY DETAILS	В ы
			Exbosm.c *	Incident Number *	noilat2	Incident Date *	* othic	FDID *	
	одо Дишћо	lod 🗌	000	9809	но	01/72/8	AM	47271	A





Massachusetts Fire Incident Reporting System - Basic

E* 419 2-FAMILY	L BROPERTY USI				c Marshal, Estimations sause and effect. Any the State Fire Marshal's	st brobable" e	ou,, puc "Apaji jsc	nerem represent truc sevalidity or accurac	petu suonenievo pue
OPERTY	I WHIXED USE PR		\$ 500,000	Contents					
asva	HAZMAT RELE		\$ 200,000	- Анэдол ^д	resontee courts	vioost bin obu	aro r⊠i Ioni	ken (3)	sT noiteA lanoitibbA
Пурпкиомп			ENT VALUE	PRE-INCID		£	_ro ⊠ _ro ⊠	1	
— i Alerted Occupants ⊠ 2 Didn't Alert Occupants	DETECTOR:		\$	Contents -	——————————————————————————————————————		- EWB		T noiro∆ InnoiribbA
ļ 0	milivi		000'9 \$	Froperty -					
	Pire Service	DuoM	000 3 3	Whymyra	23 Beisonnel	smineqqA 71	noissonqqu2	*(1) u	Primary Action Take
Deaths Injuries 2					loggostad	suffractor A		CONTROL	10 FIRE
iii	H CVSOVILLES *	nes	SSES & AVE	ES.L. \$ 1703		BCES *	C resor	*	VCLIONS LVKEN
Value Study ID# Apute Inicated Study Toler	S306 Spo		6/27/10	benselD linU les	_	Int I Montour II			L.
	2200		01/72/3 01/10	БэПошаоЭ		in Incident Nu	AM after State The	94141	Aid Given/Received
into rich simist District and simist of the contract of the co	. 0201	. (01/4Z/9	*levímA			'''	14003 15057	1 [
1 8 4	7281		01/72/8	* renslA - o	sp wrote se swes		na	17049 25035	
i I	əmil' 	1 1	onsQ		Ohook b sateb li	stances		zilidoN 01071 ☐	Incident Type
				•			10	Critical Incide	
		(0000)	sihd9indiM)S	amit & satao	 3		DEAT	* CBILICAT INC	INCIDENT TYPE
	ctions, as applicable	s ancer or direc	sorO 4 su	All Sode Ph	State			Çiiy	Apt./Suite/Room
				- 97120	AM			SOMERVILLE	
Type Suffix Census Tract	Tootil				· '	t or Highway	Prefix Stree	Number/Milepost	ı
3205	RE				-	ENMOOD	ег	113	
and bandblily no belivorg at seeibba	mobioni Ti xod sitli Abed 🔲		suo	iloonid 🔲 Ə of tri	☐ Rear of 5 ☐ Adjace] 4 10 հոօմ ոհ	Intersection 3 [∏ Sircei Address 2 ∏	TOCVLION ∗ 1 🗵
				Exposme	Incident Number *	noital2	dent Date *		* GIO3
Yiliyily oN 🔲	ograd Thango	I 🔲		100	9809	ОН	01/27/		17274





Massachusetts Fire Incident Reporting System - Fire

							ээлноў д	Piquipment Powe	
	Hatsni of a		Portable equipment normally can I be designed to be used in multiple	Portable 🔲 2 Stationary	1 🔲 :YTIJ187	PORTA			
:o.X	Serial Number		Japoy	N		buerA	noilingl ni bov	Equipment Invol	
					ŋ	ordiy2 < Skip to	DEAED IN ICN	SNIBWENL INAC	E E
	1 Male 🔲 2 Female	contally disabled	m yldisso9 4 🔲 yldissoally 🖰	(S) noitingl o	J gnitudritnoD	Toton4	nal Equipment or He Equipment or He	Intentional	
	Age was a factor Age was a factor	beningmi gurb/lodoo	onV 	OSURE (1)	Y EX			idər əmsoqxə 🏻	
	ICHILION	LOKŠ CONTRIBUTING TO	Mone HUMAN FACT	IBÚLINC LO ICHILION	OKS CONTR	FACT	* NC	OSE OF IGNITION	() E
	क्रांगयु ।	Type of Material Firs							
	NIALL	Lt							
	most tent to final beauta	* bआंत्रुवी स्थान तार्था	aged Goods for Sale irr or Service	Abe4 &	£ InirateM s	nis-nO		Veres Burned	
	NINAL SIDING	21	gnisuodaneW ac Storing Sminubanum To agnisas	Stug t 🔲			доис ress диви ове		
		Heat Source *	essing or Manufacturing aged Goods for Sale iir or Service	મુગાન દ 🗍 3 મ્હાલ	2 Inimalial 2	otis-nO	ved	loval sgaibliu8 #	
	TA3H G3TAIGAR	28	Storage or Warehousing	l Bulk		ролю	rnt toM sgniblin£	1 🗆 L	
		* nighO lo nənA	aged Goods for Sale iir or Service		I lisironsM :	olie-nO	stinU gniv	i.I to # botamited	
	EXTERIOR	. 94	Storage or Warchousing grinbanufacturing	I Bulk			feimebiseR 404	2 0	
		осиціон	<u> </u>	PRODUCTS Mone	NVLEBIVES/	C ON-SILE	ST	OBERTY DETAIL	8 В
			Exposure *	Incident Number *	noinal	* əlaC məbiənl	* oisis	* GIOT	,
	ogrange Dange	Dele	100	5809	НФ	01/27/9	AM	47271	A





Massachusetts Fire Incident Reporting System - Basic

MAT-ITJU	M 6	T	SERVE USE) BBG					ynA Jooffo	e., canse auq	ost brobabl	ա, թաթ "հլ	centacy of rep	de herein represc in validity or a	Entries contained in and evaluations and topresentation as to Office is neither inf	
		PERTY	ep nae bko	XIW			\$ s	пэтоЭ	·					(c) uang	f noiteA IsnoitibbA	
		эѕ	WYL BETEV	ZVII		000,000,1	\$ ⁴	Propert		oonreeatti x eeived resour		-				
		un n 🔲				T VALUE	IDEN	BRE-INC	3	"	ε	Оіћег	ŀ	98GU (7)	Γαοί35Α IsnoifibbΑ -	
Sundants Occupants	ried Ocer rielA l'in	I Vici	ECLOB	Lag			s	појпо	<i>b</i>		7	EWS		(6)	,; •- v ; • v	
		0	Civilian			000,1	<u> </u>	рафолд	LS			uoissəidd	lng	(1) 115	han transact Commerci	
		0	Pire Service		оноМ				Journes	a _{cl} sm	n:n:qq/			CONTROL	10 FIRE	
airmini	8	nlısəCl	* SHILIVO	svə H		SER & AVENES	ISSO″	ESL: \$1			OKCES *	RESO	ר ר פֿי		 VCLLIONS LIVKEI	H
Special Study Value	ж	al Study II	ilooq2	5306		01/12/9	p	omeD tinU :	sr 🔲	Number	ir Incident	orlT oin	ns nout lo	l* [herr FD]]	ovioos/AmoviD biA	
				2200		01/12/9	p	Controlle					AM	94141 £6041	l	D
District	smistA ,		nid2 omlq	1828		01/72/8	*	lsvirtA		·				75052 14049		
l l	ε		7	1827		01/72/9	4:	·	same as alarm date		รถอนพร	Circum	boxilide	\$2037 01041	Incident Type	_
,		,	1 1	omiT	1	Date	•		Check boxe if dates are				Juapion	I Institrical I	111	
						(0000 si MginbiN	IES (V	TES & TIN	va 🔳		•	,	INCIDENL	* CBLLICVE	INCIDENT TYPE	Э
			9	ldaoilqqa sa ,enc	or directi	Cross street	_ե sոյ _ժ	pbo 2 di	Z oms					Vii2	mooA\stiu2\.mA	1
							-)2145) AM				דרב	SOMERVI		
Serf susna	xilina	S 0	Street Typ								wigiH 10 I		iler4 soq	Mumber/Mile		
3502			ВD							D	OOMNE	פרנ]	۷۵۱		
moa busibliW	no bebiy	oud sį ssaij	oba mobioni 1i o	Check this box			suoija	oniG 🔲 do	i moosibA 🔲 8	t 🗌 Rear of	to men of	□ ε noi)	2 🔲 Intersec	ssorbbA toori≷į̇̃	FOCVLION ∗ + ⊠	8
							_≉ o.	msodxa	лиирск _*	f Insbionl	Station	* 3	ned mebient	State *	* CHOR	¬
Yiiv	iboA oM		ുവന്	ລງດ	ા Dલ			005	58	909	НС		01/72/9	AM	47271	A





Massachusetts Fire Incident Reporting System - Fire

							an Source	Powed BrandiupH	
	Alatsai of sloa		Portable equipment normally can is designed to be used in multiple	Portable 🔲 2 Stationary	ABILITY: 📋 1	PORT			
Дeш	Serial Number		loboN	Ν		bnerd	noitingl ai boy	Equipment Invol	
;					Đυ	or qids < Skip i	DEAED IN ICNI.	EÓNIBMENL INAC	L
	bevlovní nosre¶ Je ag∧ bensmitsží olicne¶ 2 □ oliciM 1 □	Poldsally disabled	3 Unadended T 4 Possibly n T 5 Physically		r Contributing to	Source Facto	nat Equipment or Mea ure	4 Act of Mat 5 Cause Und	
	Age was a factor		Aone Aslecp	SOSURE	عx∃ ا	<u>7</u> Dud	ort > Skip to section	gxbosnuc ucbe	
	TO IGNITION	LOBS CONTRIBUTING	_	NOTTING TO IGNITION	LORS CONTRI	LVA	* NC	CVOSE OF IGNITIO	B
	bolingl ren'	Type of Material I							
	TANIA	14							
	* Spread limit to first item	boning Birst Ignited	essing or Manufacturing aged Goods for Sale iir or Service	🔲 ૩ કગલ દ	£ InirateM o	Dis-nO	ouol	borrug sortoA	
	SIDING	12	Storage or Warchousing				auo unyi ssat		
	, , , , , , , , , , , , , , , , , , ,	Heat Source *	essing or Manulàcturing aged Goods for Sate irr or Service	3 Back	Z lainotaM of			lovni symblind #	
	TA3H Q3TAIQA9	28	Storage or Warchousing			paare	ovni JoM sgniblin£	'	
	ЕХТЕВІОЯ	- γ diginO lo reπΑ	Storage or Warehousing sesing or Manufacturing aged Goods for Sale or Service	oorf 2 🔲 L Back	1 IninomM 5	nie-nO	bijan Residential slinU gniv	S C C C C C C C C C	,
		контиол	1	PRODUCTS 🖾 None	MVLEBIVF?\E	C ON-SILE	ST	KOBEKLA DELVI	в в
			Exposmic *	* Incident Number	noilai2	* one of the street	* state	EDID *	
	ognañ) 🔲 c'hange		200	5809	рн	01/72/8	AM	47271	A



CITY OF SOMERVILLE, MASSACHUSETTS Fire Department

Somerville, Massachusetts 02145 266 Broadway

CHIEF ENGINEER KEVIN W. KELLEHER

> TEL.: (617) 623-1700 FAX: (617) 625-8101

June 30, 2010

to jump wondering if she would survive the 30 foot drop. we at times lost sight of her and she later told me she weighed her options whether or not not acted immediately. With heavy black smoke billowing out the window all around her, on the Delta side of the building in imminent danger of being forced to jump if they had ending. They quickly climbed the ladders and assisted the occupants out, with the woman action in rescuing two people trapped on the third floor prevented a possible tragic Michael Powers Eng. 1, FF Pat Dorant Lad. 3 and FF Ryan Epps Lad. 3. There quick outstanding performance at the 3rd alarm fire at 111 Glenwood Rd. on June 27, 2010 FF I would like to recommend that the following firefighters be recognized for their

simultaneously while the rescue was going on the first due companies E-7 and E-2 circumstances to save the lives of those two people. It should be noted that I would also like to commend the following individuals who played a major role in worked to knock down the fire and help in setting up the ladders for rescue Engine 1. It took a tremendous amount of effort and courage under extremely difficult making these rescues possible. Lt. Vince Lampley ladder 3; Lt Bryan O'Donovan, FF Tom Gorman, FF Fred Popken all of ladder 2, Capt John Keane and FF Paul French of While these three men were directly involved in the rescue

job. I am proud to recommend every one of them for a commendation. is one of the finest examples of professionalism I have witnessed in my 33 years on the house necessitating a rapid repositioning of the ladders in order to get both people out. It with temperatures around 90 and two trapped people who were in different parts of the street directly in front of the house impeding fire and rescue operations, a very hot day a downed live electrical wire that was laying across ladder 2 and dancing all over the We had to deal with a fast moving fire which had engulfed the front of the house,

Respectfully Submitted



t de la companya de l				
		(3H3H J38V)	∃o <u>≬</u> J9)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		.01	лајача иа тејооја но ти	WAKE PAYME
			usiling or delivery:	i to sserbbA. L
	Othore Elgnantes: S.A		ebnetto edt ta notslov gidt folyg	os e bejevijeb even i 🗅
	The state of the s	t more than \$200:00 (M'G:L. C:148∧ noder at the offender's last known	PRODUCTION OF THE PRODUCT OF THE PRO	Could be a served by the server of the contract of the contrac
emen reflicer refuses to state his/her name:	est of any local or state code enfor			C C C C C C C C C C C C C C C C C C C
	Date:	n.recelpt:	nder or agent to the offender upo	ећо јо етилепеје;" етем."
	e and place of the violation	or the offender's agent at the tim		
tdance with the provisions of	opos ni epiton noitsloiv ebod e	issue this Massachusetts Fir	i cerlify that (check one): 'I cerlify that (check one):	
			equent offense Date(s)of pr	
7/1/0/42 (MUN)	11-12 11 20.008.	. Saud JakomA IstoT	(on ∭ase	(C) (S) (S) (S) (S) (S) (S) (S) (S) (S) (S
	00101	-0440 /11224	aen olderschart saur	<u>''AS' ((1),044</u> ses
hamints of Alad	1842-1081 304545	14714320821411/5825	TO MADE NATE OF THE	with things
2000 S.	The state of the s			300: 100 S
	Tuəlissəssiy	illanters varbatost s	uona uona	7
nas to de corrected by: (date)	了有大型的,但是全国的政治,可是为6年的企业,但是10年的,这位10年的,但是10年的,但10年的,但10年的,10年的,10年的,10年代,10年代,10年代,	pesdus 10 °C 3º° or subseq.		(a)nothaloly (a)
illo conditions to be corrected within 24 hours ing conditions to be corrected within 24 hours	innihnoo 🔲 🚅 🚾 🧸	nsetts Regulations) <u>Check O</u>	; 527 CMR (Code of Massach). Violation(s) only	displayed the second of the se
SXINOMU	3//1/02/04	OS (GRON GOOM)	77/9/11 5M0887	72-CC-9
SOOS AT SALES		NHMEN	PA MOSI	777 // season
Con)i	-///(Estra)		\mathcal{A}_{0}	(TRALI) RIGHTERO RG BHAN
A) (12/1/27) Zy		A MASURD BY: A HALO OF FIRE DRIVENE (OR DES	2///2/Z/U souon:	CAST CASH TANK
1021=003123				



CITY OF SOMERVILLE, MASSACHUSETTS FIRE INVESTIGATION UNIT

266 Broadway Somerville, Massachusetts 02145

KEVIN W. KELLEHER CHIEF ENGINEER

TEL.: (617) 623-1700 FAX: (617) 625-8101

3 Alarms, June 27th, 2010 Incident# 10-6085 Investigators A/Capt. Christopher Major, Capt. Charles Breen, Detective Ernest Nadile Fire Box 346

FIRE INVESTIGATION REPORT

active in suppressing the fire the scene and arrived at approximately 7:04PM. The fire companies on scene were still Somerville Fire Alarm concerning a 2nd alarm fire at 111 Glenwood Road. I responded to On June 27th at approximately 6:35 PM I received a cell phone call from

INITIAL OBSERVATIONS & ACTIONS

camera and return to the scene to assist in the fire investigation. Breen was also on scene off duty. I directed him to retrieve his fire fighting gear and Road and had them standing by a few houses down from the fire scene. Captain Charles had already obtained some of the information regarding the tenants of 111 Glenwood Ernest Nadile who was working overtime as the ward six patrol officer. Detective Nadile would begin to obtain information from potential witnesses. I then met with Detective I notified the Incident Commander, Chief Kevin Kelleher that I was on scene and

proceeded to do a complete walk around of the fire building noting the damage from the exterior front of the building. After speaking with some of the neighbors, I then of fire coming from the front porch area of 111 Glenwood Road and extending up the the fire scene. (See Statements) Each neighbor stated that they observed a large volume I then began to speak with some of the neighbors located across the street from

the tenants of 111 Glenwood Road fire. Fire crews were still operating in the building so I proceeded to interview some of

couch and was always worried about people smoking there. (See Statement) smoke in the sky coming from the area of his street/house. We was worried about it being stated that he was playing basketball down at Trum Field and saw a large column of speaking with Mr. Gnatek I spoke with the other 1st floor tenant, Andrew Low. Mr. Low quite large and he could not escape via the front or side doors. (See Statement) After fire. He then had to escape the house via his bedroom window because the fire was now stairs. At this point fire began to grow and spread over the couch very quickly. He then and heat caused him to flip and drop the couch upside down blocking access to the porch couch trying to dump it over the porch railing into the side yard. As he tried this, smoke it on the couch. This seemed only to spread the flames around. He then tried to lift the located on the front porch. He stated that he tried a couple of times to get water and dump smoke a cigarette on the front porch when he observed smoke coming out of the sofa floor. Mr. Gnatek stated that he was home at the time of the fire and had gone out to in the house that you have to smoke outside either on the front porch or out in the street. porch. When asked about smoking in the house he stated that no one is allowed to smoke porch, stated that there is a couch and coffee can that is used as an ash can on the front landlord reporting the fire to him. Mr. Barnes, when asked what is usually on the front his house on fire since he stated that he knew there was smoking on the front porch at the ran back into his bedroom, grabbed his cell phone and called 9-1-1 to report the couch on After speaking with Mr. Barnes I spoke with Andrew Gnatek another tenant from the first Barnes was not home at the time of the fire but received a cell phone call from his first met with Michael Barnes, tenant of the first floor. (See Statement) Mr

property and conduct an origin and cause investigation and if any evidence was found asked Mr. Pan if he would allow members of the Fire Investigation Unit to enter the that it could be seized by the investigators. Mr. Pan signed the consent form willingly and verify, via his wife's cell phone, if all the tenants for the property were accounted for. I landlord was. The landlord, Mr. Jing Pan of 11 Ellison Road Newton, MA was trying to After speaking with the three first floor tenants I was brought over to where the

tenants of the property that were not seen at the time of the fire were accounted for stated that he was the sole owner of the property. Mrs. Pan also stated that all of the

to be pulled from the structure, the investigation into the cause and origin was begun suffered significant damage and was in danger of collapsing. Since the porch was going At this time most of the overhaul operations were complete. The front porch had

FIRE DAMAGE AND SPREAD

does not have a roof. front porch is a open aired three season porch semi enclosed. The 2nd floor front porch electrical service on the bravo side of the building, gas and water from underground. The smoke detector certificate listed the property as a 2 family residence) Utilities include bedroom door knobs. (A check of fire prevention files shows the last inspection for a the 1st, at least three on the 2rd, and at least three on the third floor had locks on all the However, at the time of this investigation it appeared that it had been remodeled into a rooming house type residence. (Single Room Occupancy) All of the bedrooms, four on The building located at 111 Glenwood Road is listed as a 2 Family residence

roof and drop ceiling damage at the front and middle of the floor from fire extending into the area between the front/middle of the apartment and near the top of the front stairway. The attic had fire windows as they failed due to the heat of the fire. The 2nd floor had fire damage at the apartment. There was fire and smoke damage to the first floor front bedroom via the front grew, it extended via the exterior of the front porch, up to the front soffit and into the attic allowed fire to extend into the stairway and up to the 2nd floor. As the intensity of the fire overlooking the front porch from the front hallway. When these windows failed it and extended up the front hallway and exterior area of the porch. There were windows The majority of fire damage appears to have started at the 1st floor front porch,

HISTORY OF PROPERTY

issued for any work at this location. The assessors' office lists the property as a two bedrooms in the attic. A check with the building department shows no permits pulled or family, however, there were at least ten bedrooms in the property finished attic. The attic was worked on sometime ago so that there are at least three 11 Glenwood Road is a wood frame building consisting of two apartments and a

FIRE INVESTIGATION

damage and possible origin of the fire photographed the scene while A/Capt. Major and Detective Nadile investigated the fire the Somerville Police Department using the Red/Blue team approach. Captain Breen Captain Charles Breen of the Somerville Fire Department and Detective Ernest Nadile The investigation of the fire was conducted by A/Capt. Christopher Major S,

pieces of charred wood that may have fallen into the can from the fire and overhauling can. The can was dragged over to the doorway and its contents examined. There were burnt into the floor boards in the area where the springs and metal wiring where found metal wiring the entire contents of the couch was consumed by the fire. There were holes couch had been dropped by Andrew Gnatek. Other than pieces of annealed springs and had extensive charring and burning on the floor and all around the wood railing where the hallway as well as from the window from the front bedroom facing the porch. The porch porch. Photos of the damage to the porch were made from the interior of the front Also within the can were numerous metal lids consistent with beer caps Against one of the interior walls of the porch was a metal can that resembled a coffee The damage to the front porch made it impossible to safely step out onto the

porch had fire damage consistent with impinging fire on the tiles. Fire had entered the door from top to bottom. The wooden shingles behind the asbestos shingles on the front The front door to the first floor had fire damage over the entire exterior of the

interior hallway to the 2nd floor hallway via the three windows located along the porch wall and communicated up the

there was a large volume of fire on the first floor front porch and extending upward as don't know how many times I had to extinguish fires from that cigarette can." Low, 1st floor tenant stating "I told people to be careful about smoking on the porch. I well as extending into the hallway via the windows. This video also showed Andrew who had videoed the fire as the first fire companies were arriving. His video showed that During the investigation Capt. Breen had interviewed a witness, Phillip Morris

Pictures of the fire origin, fire damage, and smoke detectors were taken. removed from them, or the batteries were not connected to the contacts of the detector The smoke detectors in the house did not operate because the batteries were

FIRE CAUSE & ORIGIN

on the front porch in the area of the flipped over couch. porch as well as the video of Mr. Morris, the origin of the fire is consistent with starting Based on the statements obtained, and the amount of fire damage to the front

unknown possibly rolled, in the area of the couch on the front porch. The cause of the fire is probably from careless discarding of a cigarette, type

not alerted to the fire because there were no working smoke detectors throughout the It should be noted that the tenants that had to be rescued from the third floor, were

The fire is accidental and the investigation at this time is closed

Respectfully Submitted

A/Captain Christopher Major Somerville Fire Investigation Unit