

INVOICE

INVOICE #:	SIN251662A	
INVOICE DATE:	06/13/2024	
DUE DATE:	07/13/2024	

Phone: 888-296-1381 Fax: 888-296-1384

www.feinewengland.com, AR@feinewengland.com

BILLING ADDRESS:

Attn:

SHIPPING ADDRESS:

SOMERVILLE DEPARTMENT OF PUBLIC WORKS 1 FRANEY ROAD SOMERVILLE, MA 02145 Kennedy School 5 Cherry Street Somerville, MA 02145

Approver: Mike Bowler

PROBLEM DESCRIPTION

During recent service call it was determined that the existing booster power supply next to the fire alarm system had 120v power but no voltage to NAC outputs. The existing booster power supply has failed and needs to be replaced with new. Both boosters next to the fire alarm system are Edwards boosters and synchronization cannot be achieved per code requirements. The existing fire alarm system is an Addressable Notifier and Honeywell boosters will need to be in place to accomplish synchronization. While onsite it was also determined that (10) existing Edwards pull stations in the field will need to be changed over to addressable Notifier devices.

Fire Equipment Inc will replace two existing boosters with new Honeywell Power Supplies. Speakers and Strobes will need to be sounded upon completion to verify synchronization and proper supervision. The FEI team will also replace (10) existing Edwards pull stations with new addressable Notifier devices.

WORK PERFORMED	
Repairs per quote	

CUSTOMER REFERENCE	WORK ORDER NUMBER	PURC	HASE ORDER	WORK CO	OMPLETED ON
SOMERVILLEDPW	WO-00343050	Email approval via Mike Bowler		06/13/2024	
PRODUCT NAME	DESCRIPT	ION	QUANTITY	UNIT PRICE	NET VALUE
Materials - Detection & Alarms	(2) Power Supply/Boosto	er -	1.00	\$1,445.36	\$1,445.36
Labor	Labor	Labor		\$2,063.40	\$2,063.40
Labor- Detection & Alarms	Labor- Detection & Alar	Labor- Detection & Alarms		\$3,000.00	\$3,000.00
Fire Alarm System	513D - Fire Alarm Defici	513D - Fire Alarm Deficiency		\$0.00	\$0.00

NET TOTAL:	\$6,508.76
TAX TOTAL:	\$0.00
INVOICE TOTAL:	\$6,508.76
OUTSTANDING TOTAL:	\$ 6,508.76